

# **Department of Transportation**

Rapid City Region Office 2300 Eglin Street P.O. Box 1970 Rapid City, SD 57709-1970 Phone: 605/394-2244 FAX: 605/394-1904

May 18, 2015

# ADDENDUM NO. 2

RE: May 21, 2015 Rapid City Region Office Informal Letting 000P-491, 000P-492 & 000N-491, Custer, Fall River & Pennington County PCN i3nn, i3np & i3nq Lighting Repair at various locations

# TO WHOM IT MAY CONCERN:

The following addenda to the plans shall be inserted and made part of your proposal for the above referenced project.

# **PROPOSAL:**

• Replace the DOT-123 with attached DOT-123. Arrow boards were added to the estimate of quantities for traffic control.

# PLANS:

• Replace sheets 2 thru 5 with attached sheets 2 thru 5.

Sincerely,

John Rehorst Region Design Engineer

# SOUTH DAKOTA DEPARTMENT OF TRANSPORTATION **CONTRACT PROPOSAL**

**DOT-123** (5/05)

		PROJECT		MAINT	CONTROL			BEGIN	END
CODE	PRE	ROUTE	AGR	UNIT	REFERENCE	AFE	FUNCTION	MRM	MRM
		000P		491		l3nn	2490		
		000P		492		I3np	2490		
		000N		491		I3nq	2490		

CITY AND /OR COUNTY Custer, Fall River & Pennington FINALS ENGINEER REVIEW REQUIRED L Ľ

**REGION MATERIALS CERTIFICATION REQUIRED** CERTIFIED INSPECTORS/TESTERS REQUIRED TO BE INSTALLED O TYPE, PURPOSE AN

l	BUDGET SOL
🛛 YES	
⊠YES	🗌 NO
⊠YES	🗌 NO
⊠YES	🗌 NO
Repair at va	arious locations

<u>purposes</u> SOURCE FY15 Cont. Maint.

22

ND LOCATION OF WORK	Lighting Repair at various locations
ESTIMAT	E OF QUANTITIES AND COST

BID ITEM	ITEM	QUANTITY		UNIT PRICE	AMOUNT
NUMBER	000P-491 PCN i3nn		404		
009E0010	Mobilization	Lump Sum	CLS		
634E0010	Flagging	35	Hour	\$23.55	\$824.25
634E0100	Traffic Control	1080 🗙	Unit	<u> </u>	
634E0120	Traffic Control, Miscellaneous		LS		
634E0420	Type C Advance Warning Arrow Panel		Each		
635E7510	Remove and Reset Luminaire Pole		Each		
900E2024	Miscellaneous Work, Electrical	Lump Sum	LS		
900E2030	Miscellaneous Work	9	Site		
	000P-492 PCN i3np				
009E0010	Mobilization	Lump Sum	LS		
460E0300	Breakout Structural Concrete	0.1	CuYd		
462E0100	Class M6 Concrete	0.2	CuYd		
480E0100	Reinforcing Steel	29	Lb		
480E0100	No. 7 Rebar Splice	8	Each		
634E0100	Flagging	35	Hour	\$23.55	\$824.25
634E0100	Traffic Control	1080	Unit		
634E0120	Traffic Control, Miscelaneous	Lump Sum	LS		
634E0420	Type C Advance Warning Arrow Panel	2	Each		
635E7540	Remove and Reset Luminaire Pole	3	Each		
900E2030	Miscellaneous Work	4	Site		
	000N-491 PCN i3no				_
009E0010	Mobilizati <b>o</b> n	Lump Sum	LS		_
934E0010	Rlagging	35	Hour	\$23.55	\$824.25
634E0100	Traffic Control	1080	Unit		_
634E0120	Traffic Control, Miscellaneous, Nonparticipating	Lump Sum	LS		
900E2030	Miscellaneous Work	1	Site		

#### **CONTRACTORS PROPOSAL STATEMENT**

The undersigned does hereby agree to furnish the labor and/or material in the quantities, at the unit price, for the purpose and in the place all in accordance with attached provisions upon approval of this Proposal by the State Transportation Commission. This document becomes the contract when signed by the Contractor and a Department of Transportation Representative. The Contractor agrees to provide services in compliance with the Americans with Disabilities Act of 1990. The Contractor agrees to provide a certificate of insurance prior to commencing work, for liability coverage for the duration of the work as per the current edition of the SDDOT Standard Specifications for Roads and Bridges.

PROPOSED START DATE May 21, 2015	OVE	RALL COMPLETION DATE <u>November 20,</u>	2015
SUBSCRIBED AND SWORN TO BEFORE ME THE DAY OF , 20		NY	<u> </u>
			Ser
NOTARY – My Commission Expires	FED. TAX ID	NUMBER	JIP
RECOMMENDED FOR APPROVAL:			DATE
REGION ENGINEER DATE	E	DIRECTOR OF OPERATIONS	DATE
APPROVED FOR THE TRANSPORTATION COMMIS		401	
NAME		DATE	
APPROVED as per Federal Highway Stewardship I	Provisions this	day of, 20	
APPROVED as per Federal Highway Stewardship P PROJECT DEVELOPMENT ENGINEER	-	Dolle	
	aup.		
(T)	alle		
infoli			
KOK			
x's			
nem			
10CUIL			
150-			
<n.< td=""><td></td><td></td><td></td></n.<>			

#### **ESTIMATE OF QUANTITIES**

#### PCN I3NN

Bid Item Number	Item	Quantity	Unit
009E0010	Mobilization	Lump Sum	LS
634E0010	Flagging	35.0	Hour
634E0100	Traffic Control	1,080	Unit
634E0120	Traffic Control, Miscellaneous	Lump Sum	LS
634E0420	Type C Advance Warning Arrow Panel	2	Each
635E7500	Remove and Reset Luminaire Pole	6	Each
900E2024	Miscellaneous Work, Electrical	Lump Sum	LS
900E2030	Miscellaneous Work	9	Site

#### PCN I3NP

Bid Item Number	Item	Quantity	Unit
009E0010	Mobilization	Lump Sum	LS
460E0300	Breakout Structural Concrete	0.1	CuYd
462E0100	Class M6 Concrete	0.2	CuYd
480E0100	Reinforcing Steel	29	Lb
480E0507	No. 7 Rebar Splice	8	Each
634E0010	Flagging	35.0	Hour
634E0100	Traffic Control	1,080	Unit
634E0120	Traffic Control, Miscellaneous	Lump Sum	LS
634E0420	Type C Advance Warning Arrow Panel	2	Each
635E7500	Remove and Reset Luminaire Pole	3	Each
900E2030	Miscellaneous Work	4	Site

#### PCN I3NQ

Bid Item Number	Item	Quantity	Unit
009E0020	Mobilization, Nonparticipating	Lump Sum	LS
634E0010	Flagging	35.0	Hour
634E0100	Traffic Control	1,080	Unit
634E0121	Traffic Control, Miscellaneous, Nonparticipating	Lump Sum	LS
900E2030	Miscellaneous Work	1	Site

#### SCOPE OF WORK

Work on this project involves a wide range of repairs to various types of luminaire and signal poles. Repairs consist of installing nuts, bolts and washers, replacing covers, bases, anchor systems and removing and resetting of numerous poles.

#### **SEQUENCE OF OPERATIONS**

The Contractor shall complete all work within one specific location before beginning work at another location.

Luminaire poles and luminaire heads shall remain in service during hours of darkness. Necessary repairs shall not take the luminaire out of service during the nighttime hours. The exception to this would be the luminaire pole footing extension which requires removal of the luminaire pole for several days to allow the concrete to obtain required strength. The luminaire pole shall be operational within 5 calendar days of the concrete obtaining required strength.

Repairs to signal poles shall be accomplished during non-peak hours of 7 PM to 6 AM if the repairs require the traffic signal to be taken out of service. Intersection shall be signed in all 4 directions with stop signs and all 4 way, plaques.

#### **GENERAL NOTES**

1. The Contractor shall adequately support the luminaire poles/mast arms and the signal poles/mast arms during the repair process. Any damage caused to the poles, mast arms, pole bases, or any other component of the luminaire and signals shall be repaired or replaced by the Contractor at his expense. The Engineer shall have final approval of any repairs or replacements that are required.

2. Any damage caused by the contractor to the surrounding vegetated surface, will be repaired to the satisfaction of the engineer at no cost to the State.

#### **ORIGINAL SHOP PLANS**

The SDDOT has the original shop plans for the luminaire poles on file. The SDDOT will make these original shop plans available to the successful Contractor upon award of the project if requested. These original shop plans will also be made available, upon request to RC Area Engineer Mike Carlson, to any bidders on this project if requested. Please submit requests for original shop plans to Tim.Wicks@state.sd.us

Original shop plans will be provided in PDF format.

#### **REPLACEMENT PARTS**

All replacement parts on this contract shall be obtained from the company that furnished the original luminaire components. Replacement bolts, nuts and washers shall be approved by the pole manufacturer.

Replacement parts shall have the same protective coating as the original components.

The Contractor shall be responsible for furnishing certification for replacement parts per the SDDOT Materials Manual.

#### **ORIGINAL LUMINAIRE POLE SUPPLIER CONTACT INFORMATION**

SUPPLIER Valmont Industries. Inc. http://www.valmont.com/valmont/products/pole-structures One Valmont Plaza Omaha, Nebraska 68154-5215 402-963-1000 Fax: 402-963-1198

#### SUPPLIER

Steve Klobe Inside Sales

#### SUPPLIER

http://www.ameronpoles.com/ Northwest Regional Sales Office 9661 Dutchess Place South Jordan, UT 84095 801-631-3650 Fax: 801-657-4505

#### UTILITIES

Utilities are not planned to be affected on this project. If utilities are identified near the improvement area through the SD One Call Process as required by South Dakota Codified Law 49-7A and Administrative Rule Article 20:25, the Contractor shall contact the Project Engineer to determine modifications that will be necessary to avoid utility impacts.

#### **TRAFFIC CONTROL**

Traffic control shall be per the standard plates included in this set of plans. Flaggers shall be utilized as necessary. A lane closure shall be in place if any activity impacts a lane of traffic when applicable. All lanes shall be open to traffic during non-working hours.

Removing, relocating, covering, salvaging and resetting of existing traffic control devices, including delineation, shall be the responsibility of the Contractor. Cost of this work shall be incidental to the various contract items unless otherwise specified in the plans. Delineators and signs damaged or lost shall be replaced by the Contractor at no cost to the State.

Storage of vehicles and equipment shall be as near the right-of-way line as possible. Contractor's employees should mobilize at a location off the rightof-way and arrive at the work sites in a minimum number of vehicles necessary to perform the work. Indiscriminate driving and parking of vehicles within the right-of-way will not be permitted. Any damage to the vegetation, surfacing, embankment, delineators and existing signs resulting from such indiscriminate use shall be repaired and/or restored by the Contractor, at no expense to the State, and to the satisfaction of the Engineer.

Work activities during non-daylight hours are subject to prior approval

Work zones for luminaire repair shall not exceed 1500' (4 blocks) in length without prior approval from the Engineer.

STATE OF	PROJECT	SHEET	TOTAL SHEETS
SOUTH DAKOTA	000p-491,000p-492, &000N-49	2	23
Revised 5	/14/15 jpr		

#### Millerbernd Manufacturing Company

http://www.millerberndmfg.com/steel lighting poles/

Regional Manager ND,SD & MN

Customer Service 320-485-2111 sklobe@millerberndmfg.com

# **Ameron Pole Products**

#### TRAFFIC CONTROL CONTINUED

Traffic approaching the project from intersecting roadways, streets, and approaches must be adequately accommodated. Major intersections or large commercial entrances may require additional signing, flaggers, and channelizing devices on a temporary basis until work activities pass these areas.

The bottom of signs on portable or temporary supports shall not be less than seven feet above the pavement in urban areas and one foot above the pavement in rural areas. Portable sign supports may be used as long as the duration is less than 3 days. If the duration is more than 3 days the signs shall be on fixed location, ground mounted, breakaway supports.

The Contractor shall provide documentation that all breakaway sign supports comply with FHWA NCHRP Report 350 or MASH crash-worthy requirements. The Contractor shall provide installation details at the preconstruction meeting for all breakaway sign support assemblies.

The Contractor shall accommodate pedestrian traffic, including those with disabilities. Bicycle traffic shall also be accommodated. If work shall impact the sidewalks the Contractor shall accommodate pedestrian traffic while repair work is underway with manned crossing assistance (crossing guards) combined with an accessible path. Payment for crossing guards shall be paid for under the contract item FLAGGING.

Traffic Control units, as shown in the Estimate of Quantities, are estimates. Contractor's operation may require adjustments in quantities, either more or less. The quantity of traffic control units paid for will be for the greatest number of installations per sign in place at any one time regardless of the number of set-ups on the project. Payment will be for those signs ordered by the Engineer and used on each project PCN.

In some locations work may be accomplished from behind the curb without impeding traffic. Repair locations within the City limits of Deadwood and Lead, may need to be scheduled to accommodate work areas and or special events held within these two locations. Contacts for these locations, are Ron Green @ 605-578-3082, Deadwood and John Bunch @ 605-584-1401, Lead.

#### ESTIMATE OF SIGN QUANTITIES FOR EACH PCN I3NN, I3NP,& I3NQ

SIGN CODE	SIGN SIZE	DESCRIPTION REQUIRED		UNITS PER SIGN	UNITS
E5-1a	60" x 48"	EXIT ### WITH 45 DEGREE ARROW (1 or 2 digits)	1	38	38
G20-2	48" x 24"	END ROAD WORK	1	24	24
R1-3P	16" x 18"	ALL WAYS	4	15	60
R1-1	36" x 36"	STOP	4	27	108
W3-1	48" x 48"	STOP AHEAD (SYMBOL)	4	34	136
W3-4	48" x 48"	BE PREPARED TO STOP	4	34	136
W4-2	48" x 48"	LEFT OR RIGHT LANE ENDS (SYMBOL)	2	34	68
W4-3	48" X 48"	ADDED LANE (SYMBOL)	1	34	34
W5-4	48" X 48"	RAMP NARROWS	1	34	34
W20-1	48" x 48"	ROAD WORK #### FT. OR AHEAD	5	34	170
W20-4	48" x 48"	ONE LANE ROAD ##### FT. OR AHEAD	2	34	68
W20-5	48" x 48"	LT. OR RT. LANE CLOSED ##### FT. OR AHEAD	2	34	68
W20-7	48" x 48"	FLAGGER (SYMBOL)	2	34	68
W21-5	48" x 48"	SHOULDER WORK	2	34	68
			TOTAL U	NITS	1080

#### **REPLACE LUMINAIRE POLE BASE COUPLERS**

The fluted aluminum couplers and skirting at the base of the luminaire pole shall be replaced with Transpo Pole Safe couplers and skirting. The Tables of Luminaire/Signal Repair indicate the luminaire poles which require this coupler and skirting replacement. It shall be the contractor responsibility to verify size of anchor bolts to ensure the correct couplers are purchased. It is anticipated that Model 4100 Transpo Pole Safe couplers, for 1" diameter anchor bolts will be used for replacements on this poroject.

Couplers and skirting shall be installed per Transpo Pole Safe installation instructions. Installation may require sizing of the anchor bolt projection height, cleaning of the anchor bolt, and cold galvanizing of the anchor bolt. http://www.transpo.com/pdfs/Pole-Safe Website Update/Pole Safe Design Book 2013.pdf

All costs associated with furnishing, replacing and installing the couplers and skirting shall be incidental to the contract unit price per each for REMOVE AND RESET LUMINAIRE POLE.

#### **REPLACE BOLT/BOLTS ON BACKSIDE OF MAST ARM**

The Tables of Luminaire/Signal Repair indicates signal poles which require the bolts connecting the mast arm and/or anti-rotation bolt on the arm to pole connection to be replaced.

The Contractor shall be responsible for reviewing the original shop plans and providing the proper replacement bolts. Existing washers at the connection may be reused if they are in good condition.

All costs associated with furnishing and replacing the bolt and washers at the mast arm connection to the pole shall be incidental to the contract unit price per site for MISCELLANEOUS WORK. Each signal pole requiring this work shall constitute 1 Site for payment purposes, regardless of the number of bolts requiring replacement.

#### **INSTALL BOLT, NUT AND/OR WASHER**

The Tables of Luminaire/Signal Repair indicate the luminaire pole locations which require the installation of bolts, nuts or washers on the base connection or breakaway assembly.

All costs associated with furnishing and installing bolts, nuts and or washers shall be incidental to the contract unit price per site for MISCELLANEOUS WORK. Each luminaire pole requiring this work shall constitute 1 Site for payment purposes, regardless of the number of nuts and washers installed.

The Contractor shall be responsible for reviewing the original shop plans and working with the original supplier to determine the proper hardware to install at each location.

If the installation of the bolts, nuts or washers requires removal of the luminaire pole from the luminaire base, the Contractor shall be compensated by the contract item REMOVE AND RESET LUMINAIRE POLE in addition to the contract item MISCELLANEOUS WORK.

### **TIGHTEN BOLT AND/OR NUT**

Anchor bolts shall be tightened in accordance with Section 635 of the Standard Specifications and the Supplemental Specifications to the Standard Specifications. Transformer bases shall be tightened in accordance with base manufacturer's recommendations.

The Tables of Luminaire/Signal Repair indicate the number of anchor rod nuts that were determined to be loose at the time of inspection. All anchor rod nuts at a pole location requiring anchor rod nuts to be tightened shall be torgued to the proper specifications, regardless of the number of nuts indicated to be loose.

All costs associated with tightening in place nut/nuts shall be incidental to the contract unit price per site for MISCELLANEOUS WORK. Each luminaire pole requiring this work shall constitute 1 Site for payment purposes. If the tightening requires removal of the luminaire pole from the luminaire base, the Contractor shall be compensated by the contract item REMOVE AND RESET LUMINAIRE POLE in addition to the contract item MISCELLANEOUS WORK.

# **MISCELLANEOUS WORK**

The contract item Miscellaneous Work encompasses several items of work as indicated in the various Tables of Luminaire/Signal Repair. Each item of work indicated under the contract item Miscellaneous Work shall constitute one payment of the contract item MISCELLANEOUS WORK. Thus, the Contractor may be compensated several times for the contract item Miscellaneous Work at one pole location.

# **REMOVE AND RESET LUMINAIRE POLE**

If repair work requires the removal of the luminaire pole from the pole base, the contract item REMOVE AND RESET LUMINAIRE POLE shall be paid to the Contractor in addition to any of the other contract items such as MISCELLANEOUS WORK. The Engineer shall have final authority as to when the contract item Remove and Reset Pole is paid for. Removal of the luminaire pole to make repairs to the pole or replace parts on the pole generally will not constitute removal and resetting of pole.

STATE OF	PROJECT	SHEET	TOTAL SHEETS
SOUTH DAKOTA	000p-491,000p-492, &000N-49	3	23
Revised 5			

The Tables of Luminaire/Signal Repair indicate the luminaire pole locations which require tightening of bolts and nuts.

### **REPLACE / REPAIR / SECURE HAND HOLE COVERS**

The Tables of Luminaire/Signal Repair indicate the luminaire pole locations which require repairs and or reattachment of the hand hole access covers.

If an access cover is not presently attached to the hand hole access, or the access cover is damaged, the Contractor shall furnish and install a new access cover. Replacement covers shall be pre-approved before use.

If the present attachment for the access cover is damaged and/or does not adequately secure the access cover in place, the Contractor shall be responsible for preparing and implementing a plan that adequately secures the access cover and still allows for easy removal of the access cover. Theft deterrent covers may be a potential option if the present covers and attachments are significantly damaged. The repair plan shall be approved by the Engineer prior to implementation.

All replacement materials shall have the same surface finish as the original part. If any component has the protective galvanizing damaged, the damaged area shall be repaired as per the Repair Galvanized Coating notes within these plans.

All costs associated with furnishing and installing an access cover and/or making repairs to allow for the securing of an access cover shall be incidental to the contract lump sum price for MISCELLANEOUS WORK, ELECTRICAL.

#### **REPLACE POLE CAP**

The Tables of Luminaire/Signal Repair indicate the luminaire pole locations which require installation of a luminaire pole cap. The Repair Comments in the Tables of Luminaire/Signal Repair indicate some locations where only the pole cap set screw needs to be replaced.

All costs associated with furnishing and installing a new pole cap or furnishing and installing a new pole cap set screw shall be incidental to the contract lump sum price for MISCELLANEOUS WORK, ELECTRICAL. There will be no additional compensation to the Contractor if the Repair Comments in the Tables of Luminaire/Signal Repair indicate to replace the set screw and the Contractor is required to furnish and install a new pole cap to complete the repair.

#### **REPLACE SIGNAL HEAD BACKPLATE**

The Tables of Luminaire/Signal Repair indicate the signal pole locations which require installation of a signal head backplate.

All costs associated with furnishing and installing a new signal head backplate shall be incidental to the contract lump sum price for MISCELLANEOUS WORK, ELECTRICAL.

#### **REPAIR GALVANIZED COATING**

The Tables of Luminaire/Signal Repair indicate the luminaire poles which require repair to the galvanized pole or mast arm surface.

The galvanizing repairs shall be in compliance with ASTM A 780 specifications for Zinc-rich Paint.

The steel surface shall be cleaned of all rust, scale, oil, grease and foreign matter prior to coating. The galvanizing product shall be applied according to the product application instructions.

The Contractor shall furnish the Engineer with the Zinc-rich Paint product name, application instructions and documentation that the product complies with ASTM A 780 for Paints Containing Zinc Dust.

All costs associated with repairing the galvanized surface shall be incidental to the contract lump sum price for INCIDENTAL WORK.

#### ANCHOR BOLT COVERS

The Tables of Luminaire/Signal Repair indicate the luminaire poles which require replacement of damaged or missing die cast anchor bolt nut covers.

All replacement materials shall have the same surface finish as the original part. If any component has the protective galvanizing damaged the damaged, area shall be repaired as per the Repair Galvanized Coating notes within these plans.

All costs associated with furnishing and installing new die cast anchor bolt nut covers shall be incidental to the contract unit price per each for ANCHOR BOLT COVER..

#### SHOP DRAWING AND CATALOG CUTS SUBMITTALS

The Contractor shall submit shop drawings and catalog cuts in accordance with Section 985 of the Standard Specifications or in Adobe PDF format.

Adobe PDF submittals shall be sent to the following email addresses:

Pete.Longman@state.sd.us

#### **BREAKAWAY BASES**

The Tables of Luminaire/Signal Repair indicate the locations which require installation of a new breakaway bases.

A statement is required, signed by a Professional Engineer registered in the State of South Dakota, certifying that the breakaway base devices meet the design requirements, including breakaway and structural adequacy, of the "AASHTO Specifications for Structural Supports for Highway Signs, Luminaires, and Traffic Signals". The physical testing procedures outlined in Section 8 of the Fifth Edition of the Aluminum Association's "Specifications for structural adequacy certification of aluminum breakaway transformer bases. If requested, test data of production samples to support the certification shall be provided.

All costs associated with furnishing and installing a new Breakaway Base Assembly shall be incidental to the contract unit price per site for MISCELLANEOUS WORK. Each luminaire pole requiring this work shall constitute 1 Site for payment purposes. In addition to the Breakaway Base Assembly, it requires removal of the luminaire pole from the existing luminaire base and the Contractor shall be compensated by the contract item REMOVE AND RESET LUMINAIRE POLE in addition to the contract item MISCELLANEOUS WORK.

# **REPAIR CONCRETE FOOTING**

The footing to be repaired shall consist of cleaning exposed concrete to the satisfaction of the Engineer and patched with an approved patching material from the Approved Products List. All cost to clean, form and patch footing shall be incidental to the contract unit price for INCIDENTAL WORK. Due to size of the patch, it is anticipated that the pole and base will not need to be removed to accommodate the repair of the footing.

	STATE OF	PROJECT	SHEET	TOTAL SHEETS
	SOUTH DAKOTA	000p-491,000p-492, &000N-49	4	23

																						STATE OF SOUTH	PROJECT	SHEET TOT SHEE
																					L	DAKOTA	000p-491,000p-492, &000N-49	5
																					F	Revised 5	/14/15 jpr	
										TED FALL		DEMNINCT			0000 401		0000 402		00001 3010					
										TER, FALL	(N.A.B.I.)		INCIDENTAL WORK		1 - PCN i3NN, 000P-492 - PCN I3NP, 000N-i3NQ MISCELLANEOUS WORK			ι	ELECTRICAL					
																		Replace					]	
								635E7500							Replace			Luminaire			Repair/			
N N								Remove	Eutonal						Pole to	Repair	Install bolt,	or traffic Signal	Replace	Tighten	Secure			
iect								and Reset Lumi-naire	Extend Footing						Base Coupler	damaged footing	nut and/or washer	Hardware	r Base	bolt and/or nut	hand hole covers			
Pro	Struc #	County	City	Hwy	Location Description	Latitude	Longitude	Pole (Each)	(Site)						(Site)	(Site)	(Site)	(Site)	(Site)	(Site)	(Site)		Repair Comments	
																							Install ASTM F436 /ASTM F959 heavy wa anchor rod nuts. Monitor the fine crack	
	T21000251	Custer	Custer	US16	US16 & US385	43.76354	-103.60979	1									1						coupler at the screw recess, to make sur	
	<u> </u>																						not progress. Install ASTM F436 /ASTM F959 heavy wa	ashers under t
Project No. 000P-491, PCN i3NN	T21000253	Custer	Custer	US16	US16 & US385	43.76382	-103.60967	1							1		1						anchor rod nuts. Replace the pole to ba	
	<u> </u>				US16 & Ave. of the																		to crack damage. Replace the missing shroud on the mas	
	T21000246	Custer	Rural	US16	Chiefs	43.82045	-103.63997											1					traffic signal.	st arm mounte
																							Tighten mast arm connection to the po	
				US16	US16 & Ave. of the															1			3/8" gap on the top side of the mast connects to the pole. May need to sup	
	T21000248	Custer	Rural		Chiefs	43.82004	-103.64029																arm while tightening.	
	L02678020	Pennington	Hill City	US16	Mc Gregor st and 16	43.93102	-103.57571	1								1							Repair anchorage so that anchor rod engaged.	nuts are fully
																							Two anchor rods are not long enough	
	L02678041	Pennington	Hill City	US16	16 and Deerfield	43.93408	-103.5753	1								1					1		pole base. One anchor rod nut is not f Repair or replace anchorage system. Re	
																							security to the pole.	
	102670040	Development		1164.6		42.02.455	100 57000																One anchor rod nut is loose. 1 ancho	or rod nut not
	L02678049	Pennington	Hill City	US16	Newton Ave and 16	43.93455	-103.57269	1								L	1						engaged by 3 threads Repair anchora	
	<u> </u>																						stabilize the pole and fully engage and Repair anchorage so that all anchor r	
	L02678057	Pennington	Hill City	US16	Hill City	43.93494	-103.56918	1								1							engaged with anchor rod nuts and have	e adequate roo
	L27849003	Fall River	Hot Springs	US385	Hot Springs	43.43	-103.48										1						for properly sized washer Replace missing washers on ancho	
4	L27879014	Fall River	Hot Springs		Hot Springs	43.44076	-103.47519	1	1								-		1				Extend footing to match grade elevat	tion. Replace
No. 000P N i3NP	L				SD71 and US18B Hot														-				transformer base if necessa	ary.
ect No	L27853002	Fall River	Hot Springs	US18B	Springs	43.4202	-103.47688	1								1							Repair the damage to footi	ing.
Proj	L27851002	Fall River	Hot Springs	US18B	US18 and US18B Hot Springs	43.43	-103.49	1											1				Replace transformer base	e.
oroject No. 000N-491, PCN i3NQ	T02000233	Pennington	Keystone	US16A	US16A & SD40	43.89353	-103.42522										1						Install proper washer size and material ASTM F959) under the anchor rod nut: crack at the set screw where the signal to the pole to ensure the crack does	s. Monitor th brackets mou
				1	Total Project No. 000			6	0	0	0	0	0	0	1	4	3	1	0	1	1	0		21 p. 00.000
					Total Project No. 000 Total Project No. 000			3	1 0	0	0	0	0	0	0	1	1	0	2	0	0	0	4	
							Total		1	0	0	0	0	0	1	5	5	1	2	1	1	0	1	