

May 31, 2024

**ADDENDUM NO. 1**

**RE: Item #5, June 5, 2024 Letting - IM-NH-P 0022(89), PCN 08RM, Lake, Minnehaha County -  
Grinding, Joint & Spall Repair/Pavement Repair**

**TO WHOM IT MAY CONCERN:**

The following addenda to the plans shall be inserted and made a part of your proposal for the referenced project.

**SPECIAL PROVISIONS:** NO CHANGE

**SDEBS BID PROPOSAL:** *The electronic bid proposal for this contract has been revised to include the changes associated with this addendum. Bidders must log in to the SDEBS to retrieve and incorporate these changes into their bid.*

**Quantities for Bid Items were changed:**

Bid Item 633E5100 "Grooving for Durable Pavement Marking, 4'" changed  
from 18,101 to 35,307 Ft

**PLANS:** Please destroy sheet 5 and replace with the enclosed sheets, dated 5/30/24.

**Sheet 5:** Quantities for Bid Item 633E5100 "Grooving for Durable Pavement Marking, 4'"  
changed from 18,101 to 35,307 Ft

Sincerely,

Sam Weisgram  
Engineering Supervisor

SW/cj

CC: Travis Dressen, Mitchell Region Engineer  
Harry Johnston, Sioux Falls Area Engineer

# ESTIMATE OF QUANTITIES

|                             |                             |            |                       |
|-----------------------------|-----------------------------|------------|-----------------------|
| STATE OF<br>SOUTH<br>DAKOTA | PROJECT<br>IM-NH-P 0022(89) | SHEET<br>5 | TOTAL<br>SHEETS<br>74 |
|-----------------------------|-----------------------------|------------|-----------------------|

Rev. 5/9/24 & 5/30/24 MR

## PCN 08RM

| BID ITEM<br>NUMBER | ITEM  | QUANTITY | UNIT |
|--------------------|---|----------|------|
| 009E0010           | Mobilization  | Lump Sum | LS   |
| 110E7700           | Remove Drop Inlet Frame and Grate Assembly for Reset                          | 11       | Each |
| 110E7710           | Remove Manhole Frame and Lid for Reset  | 1        | Each |
| 320E1200           | Asphalt Concrete Composite  | 200.0    | Ton  |
| 380E5030           | Nonreinforced PCC Pavement Repair   | 2,591.6  | SqYd |
| 380E5100           | Continuously Reinforced PCC Pavement Repair                                   | 46.5     | SqYd |
| 380E6000           | Dowel Bar   | 3,928    | Each |
| 380E6110           | Insert Steel Bar in PCC Pavement  | 7,145    | Each |
| 380E6200           | Tie Bar Retrofit, Stitching   | 45       | Each |
| 380E6302           | Reseal PCC Pavement Joint - Hot Pour  | 89,663   | Ft   |
| 380E6310           | Seal Random Cracks in PCC Pavement  | 1,600    | Ft   |
| 380E6510           | Grinding PCC Pavement   | 17,902.3 | SqYd |
| 390E0200           | Repair Type A Spall   | 120.0    | SqFt |
| 633E1201           | High Build Waterborne Pavement Marking Paint with Reflective Elements, White  | 99       | Gal  |
| 633E1206           | High Build Waterborne Pavement Marking Paint with Reflective Elements, Yellow | 130      | Gal  |
| 633E5100           | Grooving for Durable Pavement Marking, 4"                                     | 35,307   | Ft   |
| 633E5115           | Grooving for Durable Pavement Marking, 24"                                    | 305      | Ft   |
| 633E5120           | Grooving for Durable Pavement Marking, Area                                   | 150      | SqFt |
| 633E5125           | Grooving for Durable Pavement Marking, Arrow                                  | 9        | Each |
| 634E0010           | Flagging  | 250.0    | Hour |
| 634E0020           | Pilot Car   | 125.0    | Hour |
| 634E0110           | Traffic Control Signs   | 772.7    | SqFt |
| 634E0120           | Traffic Control, Miscellaneous  | Lump Sum | LS   |
| 634E0275           | Type 3 Barricade  | 10       | Each |
| 634E0330           | Temporary Raised Pavement Markers   | 21,500   | Ft   |
| 634E0380           | Tubular Marker  | 500      | Each |
| 634E0390           | Replace Tubular Marker  | 50       | Each |
| 634E0420           | Type C Advance Warning Arrow Board  | 2        | Each |
| 634E0600           | 4" Temporary Pavement Marking Tape Type I                                     | 150      | Ft   |
| 634E0630           | Temporary Pavement Marking  | 3.0      | Mile |
| 634E0900           | Portable Temporary Traffic Control Signal                                     | 2        | Unit |
| 634E1215           | Contractor Furnished Portable Changeable Message Sign                         | 4        | Each |
| 650E9000           | Repair Concrete Curb and/or Gutter  | 227      | Ft   |
| 670E7000           | Reset Drop Inlet Frame and Grate Assembly                                     | 11       | Each |
| 671E7000           | Reset Manhole Frame and Lid   | 1        | Each |

### SPECIFICATIONS

Standard Specifications for Roads and Bridges, 2015 Edition and Required Provisions, Supplemental Specifications and Special Provisions as included in the Proposal.