

S.D. DEPT. OF TRANS. MITCHELL REGIONAL OFFICE

TYPE OF WORK : Berm Repair, Channel Repair & Riprap at Strs 42-140-063 & 42-140-115, NW of Canton

LETTING DATE : 09/02/2014

BIDDERS				L.A. Carlson Contracting 20984 C-43 Merrill, IA 51038		Soukup Construction PO Box 89106 Sioux Falls, SD 57109		NO BID RETURNED	
BID SECURITY				Bid Bond		Annual Bid Bond			
NUMBER	ITEM	UNIT	QUANTITY	UNIT PRICE	AMOUNT	UNIT PRICE	AMOUNT		
009E0010	Mobilization	LS	Lump Sum	LUMP SUM	15000.00	LUMP SUM	20400.00		
120E0600	Contractor Furnished Borrow	CuYd	2000	20.00	40000.00	47.50	95000.00		
230E0020	Placing Contractor Furnished Topsoil	CuYd	189	25.00	4725.00	50.00	9450.00		
634E0010	Flagging	Hour	35	23.55	824.25	23.55	824.25		
634E0100	Traffic Control	Unit	374	1.00	374.00	1.50	561.00		
634E0120	Traffic Control Miscellaneous	LS	Lump Sum	LUMP SUM	1600.00	LUMP SUM	2500.00		
700E0210	Class B Riprap	Ton	178	65.00	11570.00	51.00	9078.00		
730E0212	Type G Permanent Seed Mixture	Lb	8	110.00	880.00	115.00	920.00		
730E1200	Hydroseeding	SqYd	1250	0.83	1037.50	0.90	1125.00		
732E0200	Fiber Mulching	Ton	0.5	2750.00	1375.00	3000.00	1500.00		
734E0154	12" Diameter Erosion Control Wattle	Ft	690	3.30	2277.00	3.50	2415.00		
734E0630	Floating Silt Curtain	Ft	50	27.50	1375.00	29.00	1450.00		
TOTALS				81037.75		145223.25			