#### STATE OF SOUTH DAKOTA DEPARTMENT OF TRANSPORTATION DIANS FOR PROPOSED

PLANS FOR PROPOSED

# PROJECT 3733 R SDDOT MCINTOSH STOCKPILE SITE CORSON COUNTY

#### CLASS A RIPRAP STOCKPILE



McIntosh Stockpile Site Stockpile Number 3733R Corson County (NE1/4 SEC 25 T23N R22E)



## **INDEX OF PLAN SHEETS**

SHEET NO. 1	LAYOUT MAP
SHEET NO. 2	INDEX OF PLAN SHEETS AND ESTIMATE OF QUANTITIES
SHEET NO. 3	SPECIFICATIONS & NOTES
SHEET NO. 4	STANDARD PLATES

### **ESTIMATE OF QUANTITIES**

Bid Item Number	Item	Quantity	Unit
009E0010	Mobilization	LS	Lump Sum
700E0110	Class A Riprap	250	Ton
	(McIntosh Stockpile Site) Stockpile # 3733R		

#### **SPECIFICATIONS**

Standard Specifications for Roads and Bridges, 2015 Edition and Required Provisions, Supplemental Specifications and/or Special Provisions as included in the Proposal.

#### STOCKPILE CONSTRUCTION

The Contractor shall find out the exact location to place the stockpile at and also the desired shape of the finished stockpile. If the shape and location are not done properly as per Maintenance Supervisors instructions, the Contractor shall correct the stockpile before any payment for materials is made.

#### CLASS A RIPRAP

Class A riprap shall conform to the requirements of the Specifications (Section 830) and shall be furnished by the Contractor.

The contract unit price per ton shall include all costs for furnishing and stockpiling the Class A riprap.

#### MAINTENANCE OF TRAFFIC

The Contractor shall furnish and install 48" x 48" TRUCK CROSSING signs, W8-6, to be placed on State or County highways or other well-traveled roadways. The signs shall be located a minimum of 550' in advance of intersections and approaches to the highway where the haul route crosses or turns onto/from the highway. The TRUCK CROSSING signs shall be installed for both directions of traffic travel. The exact number and location of the signs will be determined based on the pit location and haul road approved for use.

The TRUCK CROSSING signs shall be displayed at all times when the haul vehicles are hauling material from the pit to the stockpile site. During non-working hours, the signs shall be covered or removed from view. Hinged signs may be used. There will be no direct payment for the TRUCK CROSSING signs. All costs for furnishing, installation, maintenance and removal of the signs shall be absorbed in the various contract items.

#### HAUL ROADS

The Contractor shall be responsible for any haul roads used to transport material to the stockpile site. The State will not participate in the cost of restoration of any haul roads used by the Contractor.

3733R Corson County

